

To: Garmin Aviation Dealers
From: Matthew Harrah, Director, Avionics Product Support
Date: July 21, 2010

Discontinued Repair on GNS 430 28V, GNS 530 28V, and GTX 320 German

Effective September 30, 2010, the GNS 430 28V, GNS 530 28V, and the GTX 320 German will no longer be repaired due to parts availability issues.

Affected Part Numbers

011-00280-00 GNS 430 28V (010-00139-00/01)
011-00550-00 GNS 530 28V (010-00182-00/01)
011-00259-15 GTX 320 German (010-00135-15)

The GNS 430 and the GNS 530 will still be applicable for WAAS upgrade, provided no additional repairs are required for non-WAAS parts that are no longer available. Standard WAAS upgrade prices apply.

Discontinued Service Parts on GNS 430 28V, GNS 530 28V, and GTX 320 German

Effective September 30, 2010, Service Parts for the GNS 430 28V, GNS 530 28V, and the GTX 320 German will no longer be available.